

Home Remodel: Built Roughly in the 1950's this Phoenix Historical Home had tile installed throughout. The customer was looking for a mottled stained look. To begin, all the tile was removed, however, there was still quite a residue.



Heavy Mastic on the floor under the tile in the extra bedroom



This is the main room after the removal of all the mastic. As you can see there are still cracks, but they will become part of the eco-stained look.



This is the main room with the final stain and seal. Notice the saw cut that separate the two colors.



The darker color is Granite Black and the lighter color is Charcoal Black. As you can tell these colors have a bit of a brown tint, this happened because the base concrete was already colored. Stains will effect concrete differently, if the concrete is colored, if it has a higher concentrate of limestone, the age and the porosity can all be factors in how the color takes.

If you like the variegated or mottled look that you see below an eco-stain can be a beautiful and economical way to decorate your home.

Kitchen After the Removal



Kitchen Complete

